

CONTENTS

	Page
ABSTRACT.....	i
ACKNOWLEDGEMENTS.....	iii
LIST OF TABLES.....	v
LIST OF FIGURES.....	vi
LIST OF PLATES.....	vii
LIST OF EQUATIONS.....	viii
CHAPTER 1: INTRODUCTION.....	1
1.1 NATURE OF DUST.....	2
1.1.1 Definitions of Dust.....	2
1.1.2 Some Physical Properties of Dust.....	2
1.1.3 Significance of Particle Size.....	3
1.1.3.1 Impact on Efficiency of Dust-Removal Devices.....	3
1.1.3.2 Impact on Human Respiratory System and General Health.....	4
1.2 SOURCES OF DUST EMISSIONS FROM SELECTED INDUSTRIES.....	5
1.2.1 Paint and Varnish.....	5
1.2.2 Printing Ink.....	6
1.2.3 Coffee Roasting.....	6
1.2.4 Starch Manufacturing.....	6
1.2.5 Copper Smelters.....	6
1.2.6 Ferro Alloy Production.....	7
1.2.7 Gray Iron Foundry.....	7

	Page
1.2.8 Iron and Steel Mills.....	7
1.2.9 Steel Foundries.....	7
1.2.10 Asphalt Batch Plants.....	7
1.2.11 Portland Cement Manufacturing.....	8
1.2.12 Clay and Fly Ash Sintering.....	8
1.2.13 Concrete Batching.....	8
1.2.14 Glass Manufacturing.....	8
1.2.15 Stone Quarrying and Processing.....	8
1.2.16 Thermal Power Plant.....	9
 1.3 CONVENTIONAL DUST-REMOVAL DEVICES.....	 9
1.3.1 Cyclones.....	9
1.3.2 Fabric Filters.....	10
1.3.3 Wet Scrubbers.....	10
1.3.4 Electrostatic Precipitators.....	11
 1.4 ANALYTICAL TECHNIQUES FOR TRACE ELEMENT ANALYSIS IN DUST SAMPLES.....	 12
1.4.1 Atomic Absorption Spectrometry(AAS).....	13
1.4.2 Inductively Coupled Plasma-Atomic Emission Spectrometry(ICP-AES).....	16
1.4.3 Neutron Activation Analysis (NAA).....	19
1.4.4 X-Ray Fluorescence Analysis (XRF).....	20
1.4.5 Proton-Induced X-Ray Emission (PIXE).....	22
 1.5 OBJECTIVES AND SCOPE OF THE PRESENT STUDY.....	 23
1.5.1 Objectives.....	23

	Page
1.5.2 Selection of Dust-Type and Toxic Elements.....	23
1.5.3 Significance of Analysis on Bulk Dust Samples from Dust-Collecting Hopper.....	24
 CHAPTER 2: LITERATURE REVIEW.....	25
2.1 DUST POLLUTION.....	25
2.2 THE NEED TO REGULATE DUST POLLUTANTS.....	26
2.3 PARTICLE SIZE ANALYSES.....	28
2.3.1 Definitions of Particle Size Diameters: Volume Diameter, Surface Diameter, Aerodynamic Diameter, Stoke's Diameter, Projected Area Diameter, Feret's Diameter and Martin's Diameter.....	29
2.3.2 Particle Size Measurement Studies.....	30
2.4 ANALYTICAL TECHNIQUES IN DUST POLLUTION STUDIES.....	31
2.4.1 Atomic Absorption Spectrometry (AAS).....	32
2.4.2 Inductively Coupled Plasma-Atomic Emission Spectrometry (ICP-AES).....	35
2.4.3 Neutron Activation Analysis (NAA).....	39
2.5 CONCLUSION.....	43
 CHAPTER 3: MATERIALS AND METHODS.....	44
3.1 SOURCE AND SAMPLING METHODOLOGY OF DUST SAMPLES FOR THE PRESENT STUDY.....	44
3.2 PARTICLE SIZE ANALYSES.....	45
3.2.1 Instrumentation.....	45
3.2.2 Methodology.....	48
3.2.3 Calibration.....	49
3.2.4 Sample Preparation.....	49

	Page
3.2.5 Mathematical Formula for Particle Diameter.....	50
3.3 MULTI-ELEMENTAL DETERMINATIONS.....	51
3.3.1 Instrumentation.....	51
3.3.2 Sample Preparation and Treatment Apparatus.....	55
3.3.3 Standard Solutions and Reagents.....	55
3.3.4 Digestion Methodology.....	56
3.4 ANALYTICAL QUALITY CONTROL PROCEDURES.....	60
3.4.1 Quality Control in Field Sampling.....	61
3.4.1.1 Sampling Protocol.....	61
3.4.1.2 Dust Sample Collection.....	61
3.4.2 Quality Control in Laboratory Analysis.....	62
3.4.2.1 General Precautions.....	62
3.4.2.2 Analysis of Particle Size.....	62
3.4.2.3 Analysis of Standard Reference Materials.....	62
3.4.2.4 Analysis of Reagents/Sample Blanks.....	63
3.4.2.5 Calibration with Standards.....	63
3.4.2.6 Analysis of Replicates.....	64
3.4.2.7 Accessories.....	64
3.5 DATA COMPUTATIONS AND STATISTICAL ANALYSES.....	64
3.5.1 Particle Size Diameter and Distribution Statistics.....	64
3.5.2 Multi-elemental Determinations.....	66
3.6 RELATIONSHIP BETWEEN PARTICLE SIZE DIAMETER AND CHEMICAL CONCENTRATIONS.....	66

	Page
CHAPTER 4: RESULTS AND DISCUSSION.....	67
4.1 SOURCE AND GENERATION OF TWO DUST TYPES AT THE PAINT MANUFACTURING PLANT.....	67
4.2 PARTICLE SIZE ANALYSES.....	67
4.2.1 Solvent-Based Paint Dust.....	67
4.2.1.1 Particle Size Diameter D(4,3).....	67
4.2.1.2 Particle Size Diameter:Cumulative Distribution Patterns.....	69
4.2.2 Water-Based Paint Dust.....	71
4.2.2.1 Particle Size Diameter D(4,3).....	71
4.2.2.2 Particle Size Diameter:Cumulative Distribution Patterns.....	72
4.2.3 Comparison of Cumulative Distribution Curves for Solvent-Based and Water-Based Paint Dust.....	74
4.3 ELEMENTAL COMPOSITION AND CONCENTRATIONS IN DUST SAMPLES.....	75
4.3.1 Preliminary Analyses.....	75
4.3.2 Solvent-Based Paint Dust.....	76
4.3.3 Water-Based Paint Dust.....	77
4.3.4 Comparison of Chemical Concentrations of the Four Selected Elements for Solvent-Based Paint Dust and Water-Based Paint Dust.....	79
4.4 COMPARISON OF PARTICLE SIZE DIAMETERS AND THE CHEMICAL CONCENTRATIONS.....	79
CHAPTER 5: GENERAL DISCUSSION.....	81
5.1 COMPLIANCE WITH ENVIRONMENTAL QUALITY (CLEAN AIR) REGULATIONS, 1978.....	84

	Page
5.2 PROCESS DESCRIPTION.....	85
5.2.1 Solvent-Based Paint.....	85
5.2.2 Water-Based Paint.....	86
5.3 WASTE DESCRIPTION:.....	87
5.4 DUST POLLUTION PREVENTION OPTIONS.....	88
5.4.1 Process Modifications.....	88
5.4.2 Resource Recovery and Recycling.....	88
5.4.3 Good Housekeeping and Operating Practices.....	89
CHAPTER 6: SUMMARY.....	90
REFERENCES.....	94
APPENDICES.....	102
A: A Sample of Raw Data on Particle Size Analyses for Solvent-Based and Water-Based Paint Dust.....	103
B: Mercury Alignment Curve.....	105
C: Calibration Curves for As, Cu, Pb and Zn.....	106
D: Questionnaires.....	110
E: Addenda.....	111