

TABLE OF CONTENTS

Original Literary Work Declaration	ii
Abstract	iii
Acknowledgements	vii
Table of Contents	viii
List of Figures	xiv
List of Tables	xxiv
List of Symbols and Abbreviation	xxv
List of Appendices	xxvii
1.0 INTRODUCTION	
1.1 Background	1
1.2 Significance of the Study	5
1.3 Aims and Objectives of the study	6
1.4 Scopes of works	7
1.5 Outline of the thesis	9
2.0 LITERATURE REVIEWS	
2.1 Introduction	11
2.2 Seawater Intrusion at coastal area	13
2.2.1 Studies of seawater intrusion at coastal area in Malaysia	15
2.2.2 Cause of seawater intrusion into groundwater aquifer at coastal area of Malaysia	18

2.3	Groundwater system in coastal area	20
2.3.1	Groundwater system in coastal area of Peninsular Malaysia	23
2.3.2	Regional Hydrogeology of Langat Basin	25
2.4	Agriculture activities in coastal area of Peninsular Malaysia	34
2.4.1	Salinity effects on plant at coastal area	34
2.4.2	Overview of oil palm plantation of coastal area in Malaysia	37
2.4.3	Oil palm physiography and salinity tolerance	38
2.5	Overview of Carey Island	42
2.5.1	Rainfall	43
2.5.2	Hydrogeological of Carey Island	46
2.5.3	Socioeconomic Activities	54
2.5.4	Carey Island's history of groundwater use and present water supply status	54
2.5.5	Land Use	58
2.6	Summary	60
3.0	METHODOLOGY AND DATA ACQUISITION	61
3.1	Introduction	61
3.2	Surface Study	63
3.2.1	Surface Mapping	63
3.2.1.1	Land-Use and Drainage	63
3.2.1.2	Surface Elevation	64

3.2.2	Precipitation and Sea Tide	71
3.2.2.1	Precipitation	71
3.2.2.2	Sea Tide Study	72
3.3	Subsurface Hydrogeology Study	76
3.3.1	Procedures for Drilling and Material Sampling	77
3.3.2	Procedures for soil tests	79
3.3.3	Procedure for acquiring subsurface hydrogeology	81
3.3.4	Data integration for hydrogeological profiles	81
3.3.5	Groundwater Monitoring	84
3.3.5.1	Procedures of Monitoring Wells Construction	84
3.3.5.2	Procedures for Groundwater Sampling and Monitoring	90
3.3.6	Procedures for Groundwater Quality Tests	94
3.3.6.1	Physical Test	94
3.3.6.2	Chemical Test	96
3.3.7	Classification of groundwater salinity	97
3.3.8	Groundwater Monitoring Data	98
3.4	Subsurface Resistivity Survey	102
3.4.1	Data acquisition procedure	106
3.4.2	Data Collection and Processing	109
3.4.3	Pre-inversion methods to remove bad data points	110
3.4.4	Data Interpretation	116
3.5	Correlation between Earth Resistivity and Groundwater Quality	119
3.6	Pore fluids Resistivity Calibration	121

3.7	Time-Lapse Resistivity Tomography Measurement (TLERT)	123
3.8	Statistical Analysis	124
3.9	Resistivity and Conductivity Contours	124
3.10	Summary	124
4.0	HYDROGEOLOGY CHARACTERISTICS OF CAREY ISLAND	126
4.1	Introduction	126
4.2	Summary of Surface Study Results	128
4.2.1	Land-Use Activities	128
4.2.2	Surface Elevation	128
4.2.3	Drainage Distribution	128
4.2.4	Precipitation and Sea Tide Study Results	135
4.3	Analysis of surface study	139
4.3.1	Land use activities	139
4.3.2	Surface elevation	140
4.3.3	Drainages distribution	140
4.3.4	Precipitation and Sea Tide Study	141
4.4	Summary of Subsurface Hydrogeology Results	142
4.4.1	Subsurface Hydrogeology Mapping and Profiles	142
4.4.2	Groundwater Tables	150
4.4.3	TDS Monitoring	153
4.4.4	Chemical Testing	156
4.5	Analysis and Results Integration	157
4.5.1	Subsurface hydrogeology mapping and profiles	157
4.5.2	Salinity distribution (TDS)	163

4.5.3	Groundwater table versus seasonal	164
4.5.4	Groundwater table versus sea tides	169
4.5.5	Groundwater table versus TDS	171
4.5.6	Source of salinity	174
4.6	Summary	175
5.0	SUBSURFACE RESISTIVITY RESULTS AND CORRELATION WITH GROUNDWATER QUALITY	178
5.1	Introduction	178
5.2	Subsurface Resistivity Results	180
5.3	Correlation between subsurface resistivity and water types	188
5.4	Field calibration	193
5.5	Time-Lapse Electrical Tomography (TLERT) Measurement Results	196
5.6	Summary	203
6.0	GROUNDWATER SALINITY DISTRIBUTION AND IMPACT TO AGRICULTURE ACTIVITIES	205
6.1	Introduction	205
6.2	2-D Subsurface resistivity results (second phase)	206
6.2.1	Resistivity profiles L6-L6', L7-L7' and L8-L8'	208
6.2.2	Resistivity profiles L1-L1' and L5-L5'	209
6.2.3	Resistivity profile L14-L14'	209
6.2.4	Resistivity profile L15-L15'	209
6.2.5	Resistivity profile L16-L16'	210

6.3	3-D resistivity mapping for groundwater salinity distribution	214
6.4	3-D conductivity mapping for agriculture activities	222
6.5	Impact of sea-level rise to groundwater salinity and agriculture activity in Carey Island	232
6.6	Summary	234
7.0	CONCLUSION AND RECOMMENDATIONS	235
7.1	Introduction	235
7.2	Recommendations for future work	243
8.0	REFERENCES	